

OUT55452

1965 APR 12 21 34Z

13 APR 19625X1

CyNo.	Office	Act.	Rc
L	Main File		
	US		
	ADMIN		
	SPECIALER		
	PERS		
	GEO		
FIRST	ID		
E 3.4			
INBOARD			
OCCURRED			
	DIAAP		
IILM	Destroyed		

## 1

B. 9R SIDE: ROWS OF MINUS DENSITY DOTS OCCUR SPACED 1.55" APART AND LOCATED 4.7" AND 5.5" FROM THE INBOARD EDGE IN THE FIRST 57 FRAMES, AND 4.2" AND 7.9" FROM THE SAME EDGE THROUGHOUT THE MISSION. EVIDENCE OF MINOR PRESSURE ROLLER STATIC ALONG THE INBOARD EDGE EXISTS THROUGHOUT THE MISSION. A MANUFACTURING SPLICE OCCURRED IN FRAME 1513. A HEAT SPLICE IS PRESENT IN FRAME 1209. FINE EMULSION SCRATCHES ARE LOCATED PARALLEL TO THE EDGES OF THE FILM THROUGHOUT THE FIRST TWO PARTS OF THE MISSION.

GROUP 1  
25X

**SECRET**

ASSOCIATED STATIC MARKS ON 1894. BECAUSE THERE WAS NO TAPE SECURING THE LEADER ON THE HEAD OF EACH PART, EXTREME CARE HAD TO BE EXERCISED TO PREVENT DAMAGE TO THE FILM WHEN EXTRACTING THE REEL OF FILM FROM THE CAN.

D. BOTH SIDES: EVIDENCE OF EDGE STATIC IS PRESENT ALONG BOTH SIDES OF THE FILM THROUGHOUT THE MISSION. THE TITLED FRAMES ARE NUMBERED CONSECUTIVELY FROM 0000 TO 2344 ON THE 9L SIDE AND THERE IS ONE ADDITIONAL FRAME ON THE 9R SIDE.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS COVERAGE IS LESS THAN 10 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/